

Items Included in part number 3088.031 Gasket Kit SAB 128 Mk1 - 4 Rotor Inspection

Part No	Designation	Qty.	Pos No.	Item Image
1331.536	O-ring HNBR 14.00x1.78 Size-015	3	26/96	
1331.571	O-ring HNBR 85.32x3.53 Size-237	3	81/5B/91/6B/12C	
1331.573	O-ring HNBR 91.67x3.53 Size-239	2	152/12D	
1331.595	O-ring HNBR 304.39x3.53 Size-278	1	21/4B	
1331.697	O-ring HNBR 82.14x3.53 Size-236	2	154	
3049.006	Gasket 13.5/8x4/2	8	143/H1	