






Items Included in part number 3088.054 Gasket Kit SAB 202 Rotor Inspection


Part No	Designation	Qty.	Pos No.	Item Image
1331.427	Dowty ring ø23.80/ø17.28X2.03	2	149B	
1331.540	O-ring HNBR 13.94x2.62 Size-113	1	49	
1331.547	O-ring HNBR 9.12x3.53 Size-204	1		
1331.549	O-ring HNBR 21.82x3.53 Size-212	1	49X	
1331.565	O-ring HNBR 63.09x3.53 Size-230	1	160C	

1331.568

O-ring HNBR 75.79x3.53  
Size-234

1

160D




1331.583

O-ring HNBR 132.94x3.53  
Size-252

1

164




1331.585

O-ring HNBR 142.47x3.53  
Size-255

2

154







1331.586

O-ring HNBR 151.99x3.53  
Size-258

1

43



1331.587	O-ring HNBR 158.34x3.53 Size-259	1	166	
1331.596	O-ring HNBR 430.66x3.53 Size-283	1	21	
2114.045	Washer SAB 202	6	143	
2132.100	Tape bearing 10x0.96x270 PTFE	2	209	
2132.118	Tape bearing 10x2.5x336 PTFE	2	140-1/-2	